

CICA - SWLRT

A pictorial overview of the impact to CICA both along the Kenilworth Trail and in the indoor common areas




Kenilworth Trail next to CICA Parking deck 6-5-2019

CICA 3151 west tower prior to beginning of construction including private resident garden 5-19-2020



Proximity to CICA 3151 west tower
5-26-2020



VIBRATION MONITORING
IN PROGRESS
DO NOT
1-

Proximity to CICA 3151 west tower 5-26-2020




Proximity to CICA 3151 tower 3-9-2021




3151 8th floor cracks
10-8-2022

SCRIPT TRANSCRIPT TRANSCRIPT
3151 8
3151 8
3151 8



3151 8th floor repair bracing 10-18-2022

3141 10th floor bracing diagram 10-18-22



3141 10

CICA- new garage door damage 9-6-2023



**Tunnel work adjacent to CICA parking deck and garage wall 9-6-2023
view to southwest**



Tunnel construction adjacent to parking deck and garage wall 9-6-2023



**Drilling next to CICA
10-26-2022**



12th floor elevator lobby to penthouse units 5-8-2023



3151 10th floor elevator lobby
monitor and damage
1-5-2024



3151 10th floor resident hallway ceiling
1-5-2024





3151 10th floor monitor
1-5-2024

**3151 10th floor
carpet separation, floor and wall cracks
1-5-2024**




3151 10th floor resident corridor floor and wall cracks
1-5-2024



3151 10th floor floor and wall cracks 1-5-2024





3141 10th floor elevator lobby 1-5-2024